

# Case Story

## Dust filtration from cast iron milling in train repair workshops

**Situation:** A large train repair workshop in south Italy had a lot of severe problems with cast iron dust and fumes, spread into the air from big milling machines.



**Solution:** Two Filtermax 3000 units and one Filtermax 9000 unit were installed in three different maintenance workshops and connected directly to the cast iron milling machines. The purified air is recirculated into the working environment.

**Benefits:**

- The customer has expressed great satisfaction with Nederman solution of high quality products.
- The high efficiency filtration has finally transformed the workshop into a clean working area, free from dust.